
DI912-01

ACC Power Source Circuit

CIRCUIT DESCRIPTION


This is the power source for A/C amplifier and servomotors, etc.

WIRING DIAGRAM



INSPECTION PROCEDURE

Check voltage between terminals ACC and GND of A/C amplifier connector.



PREPARATION:


Remove A/C amplifier with connectors still connected.

CHECK:

- (a) Turn ignition switch ON.
- (b) Measure voltage between terminals ACC and GND of A/C amplifier.

OK:

Voltage: Battery positive voltage




OK


Proceed to next circuit inspection shown on problem symptoms table (See page DI-130).



1

Check continuity between terminal GND of A/C amplifier and body ground. 2






CHECK:

Measure resistance between terminal GND of A/C amplifier and body ground.

OK:


Resistance: 0 Ω (continuity)



NG Repair or replace harness or connector.



3 Check IGN fuse.



PREPARATION:

Remove IGN fuse from cowl side J/B.

CHECK:

Check continuity of IGN fuse.

<u>OK:</u>

Continuity

NG

Check for short in all the harness and components connected to the IGN fuse (See attached wiring diagram).

OK

Check and repair harness and connector between A/C amplifier.