


MULTIPLEX COMMUNICATION SYSTEM

HOW TO PROCEED WITH TROUBLESHOOTING

DI310-03

Perform troubleshooting in accordance with the procedure on the following page.



Step 4, 8 : Diagnostic steps permitting the use of the TOYOTA hand –held tester.