

21. GPS mark does not appear.

INSPECTION PROCEDURE

- | | |
|---|--|
| 1 | Check the mark display. (At a place with a fine view, is GPS mark displayed or not?) |
|---|--|

Yes

Normal.

No

- | | |
|---|--|
| 2 | Check if the harness is caught or sharply bent or not. |
|---|--|

NG

Navigation antenna is surely connected.

OK

- | | |
|---|--|
| 3 | Check optional components. (Does it become normal if the optionals such as the theft deterrent system is removed?) |
|---|--|

Yes

Remove or change the position of the components.

HINT:

Some optionals receive radio signals, and if this happens, GPS reception may be affected.

No

4 Is there anything such as a film stuck to the window?

Yes

Reception may be affected by a screen such as a film.

No

5 Service check mode. (Is "80-40, 41" is displayed in the unit check mode of the navigation ECU?)

Yes

Troubleshoot for each diagnosis.

No

Replace the navigation antenna.

HINT:

If the trouble still occurs, replace the navigation ECU.