
DI891-02

## 30. CD magazine inserted, but no power.



YES

Radio receiver assembly faulty.

5 Is power supplied to ACC terminal of CD auto changer?

NO Radio receiver assembly faulty.

YES

DVD auto changer faulty.