DI89.I-02

31. Power coming in, but CD auto changer not operating

INSPECTION PROCEDURE Is CD inserted with correct side up? 1 NO Insert correctly. **YES** Function OK if different CD magazine inserted? 2 CD magazine faulty. **YES** NO Is radio operating normally? 3 **YES** Go to step 7. NO Does contunuity exist in speaker wire harness? 4 NO Speaker wire harness faulty. **YES**

5	Temporarily install another s	peaker. Function OK?
		YES Speaker faulty.
NO		
6	Hiss noise from speaker?	
		NO Power amplifier faulty. Recheck system after repair.
YES		
Radio assembly faulty. Recheck system after repair.		
7 Is temperature inside cabin hot?		
		YES Protective circuit in operation.
NO		
8	Has sudden temperature cha	nge?
		YES Formation of condensation due to temp. changes.
NO		
CD auto changer faulty.		