DI89L-02

33. Sound quality poor (volume faint)

INSPECTION PROCEDURE

1 Function OK if another CD is played?

Yes

CD faulty.

No

2 Is radio operating normally?

Yes

Radio receiver assembly faulty.

No

3 Is speaker properly installed?

No

Install properly

YES

4 Temporarily install another speaker. Function OK?

Yes

Speaker faulty.

No

Radio assembly or CD auto changer or power amplifier faulty.