

## 21. GPS mark does not appear.

### INSPECTION PROCEDURE

- |   |  |
|---|--|
| 1 | Check the mark display (At a place with a fine view, is GPS mark displayed or not?). |
|---|--|

Yes

Normal.

No

- |   |  |
|---|--|
| 2 | Check if the harness is caught or sharply bent or not. |
|---|--|

NG

Navigation antenna is surely connected.

OK

- |   |  |
|---|--|
| 3 | Check optional components (Does it become normal if the optionals such as the theft deterrent system is removed?). |
|---|--|

Yes

Remove or change the position of the components.

HINT:

Some optionals receive radio signals, and if this happens, GPS reception may be affected.

No

**4** Is there anything such as a film stuck to the window?

**Yes**

Reception may be affected by a screen such as a film.

**No**

**5** Service check mode (Is "80-40, 41" is displayed in the unit check mode of the navigation ECU?).

**Yes**

Troubleshoot for each diagnosis.

**No**

**Replace the navigation antenna.**

HINT:

If the trouble still occurs, replace the navigation ECU.