DI89F-01

# 27. Cassette tape cannot be eject.

# **INSPECTION PROCEDURE**

1 Check if ACC or DOME fuse is OK?

NG

Replace fuse.

OK

2 Check the radio receiver assembly.

## **PREPARATION:**

Disconnect the radio receiver assembly connector.

#### **CHECK:**

Check voltage terminals +B.

OK:

+B: 10 - 14 V

## **CHECK:**

Check voltage terminal ACC when turn ignition switch ACC or ON position.

OK:

ACC: 10 - 14 V

# **CHECK:**

Check continuity terminal GND.

<u>OK:</u>

**GND: Continuity** 

NG )

Replace or repair wire harness.

#### HINT:

When sending it for repair, leave as it is without attempting to take it out by force.

OK

Replace the radio receiver assembly.