


## ■ INTERIOR

### 1. Instrument Panel


- The design of the center cluster has been changed.
- The design of the combination meter has been changed. For details, refer to the Combination Meter section of the [page 239](#).



229LC106

### 2. Pillar Garnish and Roof Side Portion

- The designs of the center pillar garnish and roof side portion have been changed.
- The design of the assist grip and coat hook have been changed on the model with the curtain shield airbags.



229LC107